

Mt Robson Visitors Centre ▼

Information

Date of Audit: 2016-09-21

Park Name: Andy Bailey

Key Features: Camping,Picnic_Site,Fishing

Location: Northern Rockies, Fort Nelson, Northern BC - Regional : Park (Great Northern Circle Route)

Description:

Parking

Access Routes

Trails

Washrooms


Camping

Date of Audit (YYYY-MM-DD) : 2016-09-21

Name of Campground : Andy Bailey Regional Park Campground

Location of Campsite : Park is located 12 km right off the Alaska Highway at mile marker 265 or traveling south from Fort Nelson for approximately 28 km turn left for 12 km

Weather condition during audit : Sunny



1. Does the number of accessible camp sites comply with the table above? : No_-_Below_Standard (Rating: 0)

Comments/Description : The camp sites have a solid foundation and are flat. A few tables, and accessible pit toilet, would help to accommodate all abilities

Campsite

2. Is the camp site surface firm and stable? : Yes (Rating: 1)

3. What type of surface is in the campsite? : Grass

Comments/Description : and packed gravel

4. Is the accessible campsite at least 4.9m wide?

Or : N_A (Rating: 0)

Comments/Description : The campsites are large enough that they could be

5. If it is an RV site, is the parking area at least 6m wide? : N_A (Rating: 0)

6. If the campsite surface is concrete or asphalt, is the slope 1° or less? : N_A (Rating: 0)

**7. If the campsite surface is anything other than concrete & asphalt, is the slope 3° or less? : Yes -
_Meets_Standard (Rating: 1)**

Tent Pads/Platforms

**8. Is there a minimum of 1220mm clear space on all sides surrounding the tent pad or platform? : Yes -
_Exceeds_Standard**

9. What type of surface is the tent pad/ platform? : Grass

10. What is the slope of the tent pad/ platform? : Moderate_2_-_3 (Rating: 1)

Comments/Description : it is mostly flat and gentle

11. Is there an accessible entrance or ramp on to the tent pad/platform? : No (Rating: 0)

Utility & Sewage Hook Ups

**12. Is there sufficient clear ground space, a minimum of 1220mm x 1525mm surrounding the hook ups? :
N_A (Rating: 0)**

**13. If there are operable parts, can they be operated using one hand, without tightly grasping, pinching, or
twisting the wrist and with no more than 2.3kg of force? : N_A (Rating: 0)**

Campfires & Grills

14. Is there an area for campfires? : Yes (Rating: 1)

Comments/Description : some fire pits, some, rocks in a circle

Recommendations : Fire pits would be better

15. Is there a minimum of 1220mm clear ground space on all sides? : Yes - _Exceeds_Standard

Comments/Description : They are not in every campsite, but where they are is plenty of room

16. Is the slope 3° or less in all directions? : Yes (Rating: 1)

17. Is the grill height between 380mm - 865mm above the ground? : N_A (Rating: 0)

Comments/Description : no grills just a fire ring

18. Is the fire building surface height at least 230mm above the ground? : No (Rating: 0)

19. If there is a raised edge or wall around the fire building area, is the thickness less than 255mm? : N_A

(Rating: 0)

20. Is there a clear, level accessible route to the campfire area? : Yes (Rating: 1)

Comments/Description : All campsites are flat and gentle to fire pit or ring.

21. Are picnic tables provided? : Yes (Rating: 1)

22. How many accessible picnic tables are there? : N_A

Comments/Description : there are no accessible tables

23. If the picnic table is up to 2.7m long, is there one wheelchair seating space? : N_A (Rating: 0)

24. If the picnic table is longer than 2.7m, are there at least two wheelchair spaces provided? : N_A (Rating: 0)

25. Is there clear and level ground space, 915mm measured from back edge of seats/benches? : Yes - _Meets_Standard (Rating: 1)

Comments/Description : The ground is level and hard around the picnic tables, an accessible one could be switched out easily

26. Do the accessible spaces have adequate knee clearance, 685mm high x 760mm wide x 430mm deep? : N_A (Rating: 0)

27. Is the ground surface surrounding the accessible picnic table firm and stable? : N_A (Rating: 0)

Comments/Description : The ground around existing tables could easily sustain an accessible table

28. Is there a clear, level accessible route to the picnic table? : N_A (Rating: 0)

Comments/Description : The ground is level and hard around the existing tables

Water Taps

1. Are there any water taps? : Yes (Rating: 1)

Comments/Description : There is a water pump

2. Is there sufficient clear ground space, a minimum of 1829mm x 1220mm surrounding the water tap? : Yes - _Meets_Standard (Rating: 1)

Comments/Description : The pump is located on a cement pad, it has a bit of a ridge on one side but is even with the ground on the other side

3. Is the water spout height between 280mm - 305mm? : Yes (Rating: 1)

Measurement (mm) : 305

4. Is the height of operable parts (i.e. taps or levers) between 380mm - 1220mm above the ground? : Yes (Rating: 1)

**Measurement
(mm) : 1000**

Comments/Description : The pump handle can be lifted to 1000mm

5. If there are operable parts, can they be operated using one hand, without tightly grasping, pinching, or twisting the wrist and with no more than 2.3kg of force? : No (Rating: 0)

Comments/Description : A little difficult with one hand

6. Is there a clear, level accessible route to the water tap? : Yes (Rating: 1)

Comments/Description : It is accessible from the road

Water Fountains

1. Is there a water fountain? : No (Rating: 0)

2. Does it have a lever or push bar control on the front or both sides? : N_A (Rating: 0)

3. Is the spout opening height between 750mm - 915mm above the ground? : N_A (Rating: 0)

4. Is there a minimum width of 800mm clearance space directly in front of the water fountain? : N_A (Rating: 0)

5. Is there a clear, level accessible route to the water fountain? : N_A (Rating: 0)

Trash & Recycling Receptacles

1. Are there any trash &/or recycling receptacles? : Yes (Rating: 1)

2. Is the approach to the receptacle level, with no-step? : Yes (Rating: 1)

3. If there are operable parts, is their height between 380mm - 1220mm above the ground? : Yes (Rating: 1)

4. If there are operable parts, can they be operated using one hand, without tightly grasping, pinching, or twisting the wrist and with no more than 2.3kg of force? : Yes (Rating: 1)

5. Is there a clear, level accessible route to the trash/recycling receptacle? : Yes (Rating: 1)

Shelters

1. Are there any camp shelters? : No (Rating: 0)

2. What is the slope at the entrance to the camp shelter? : N_A (Rating: 0)

3. What type of surface is in the camp shelter? : N_A

4. Is the shelter surface firm and stable? : N_A (Rating: 0)

5. Is there a clear, level accessible route to the camp shelter? : N_A (Rating: 0)

Benches

1. **Are any benches provided?** : No (Rating: 0)
2. **If yes, how many benches are there?** : N_A
3. **Is the bench seat height between 485mm - 510mm?** : N_A (Rating: 0)
5. **Is there a clear, level accessible route to the bench?** : N_A (Rating: 0)

Playground

1. **Is there a playground?** : No (Rating: 0)
- 2 **What type of surface is in the play area?** : N_A
3. **Is the play area surface firm and stable?** : N_A (Rating: 0)
4. **Are any of the playground components accessible to wheelchair users? If yes, please describe.** : N_A (Rating: 0)
5. **Is there a clear, level accessible route to the playground?** : N_A (Rating: 0)

Amphitheatre

1. **Is there an amphitheatre?** : No (Rating: 0)

Amphitheatre Seating

2. **Are an adequate number of wheelchair spaces provided?** : N_A (Rating: 0)
3. **Are wheelchair spaces dispersed to allow location choices and viewing angles equivalent to other seating, including specialty seating areas that provide distinct services and amenities?** : N_A (Rating: 0)
4. **Where people are expected to remain seated, do people in wheelchair spaces have a clear line of sight over and between the heads of others in front of them?** : N_A (Rating: 0)
5. **Where people are expected to stand, do people in wheelchair spaces have a clear line of sight over and between the heads heads of others in front of them?** : N_A (Rating: 0)
6. **If there is a single wheelchair space, is it at least 915mm wide?** : N_A (Rating: 0)
7. **If there are two adjacent wheelchair spaces, are they each at least 840mm wide?** : N_A (Rating: 0)
8. **If the wheelchair space can be entered from the front or rear, is it at least 1220mm deep?** : N_A (Rating: 0)
9. **If the wheelchair space can only be entered from the side, is it at least 1525mm deep?** : N_A (Rating: 0)
10. **Do wheelchair spaces adjoin, but not overlap, accessible routes?** : N_A (Rating: 0)
11. **Is there at least one companion seat for each wheelchair space?** : N_A (Rating: 0)
12. **Is the companion seat located so the companion is shoulder-to-shoulder with the person in a wheelchair?** : N_A (Rating: 0)

13. Is the companion seat equivalent in size, quality, comfort and amenities to seating in the immediate area? : N_A (Rating: 0)

2. Are there any public buildings (visitors centre/ interpretive centre/cafes etc) at the campground? : No (Rating: 0)

3. Are there any trails at the campground? : No (Rating: 0)

**4. Is there a beach, dock/fishing platform or boat launch? : Yes -
_WATER_ACCESS_checklist_must_also_be_completed (Rating: 0)**



Description of Photo 1 : Path from secluded picnic area to beach front picnic and tenting area



Description of Photo 2 : The lake is visible through the trees on the left hand side, there are a few rough trails through the bush



Description of Photo 3 : Inaccessible pit toilets visible through the trees



Description of Photo 4 : Huge camping or picnic area close to boat launch. I think it could also be used for parking as there was no designated area

Water Access


Date of Audit : 2016-09-21

Body of water : Lake

Location : The lake and campsite are located at mile marker 265 on the Alaska Highway and 12 km off the

highway. If leaving from Fort Nelson it is 27.6 km south and turn left for 12 km

Weather condition during audit : Sunny



Parking

1. Is parking provided for the public? : No (Rating: 0)

Comments/Description : There is not a lot of parking unless you are using the campsites,

2. Are an adequate number of accessible spaces provided? : N_A (Rating: 0)

3. Of the accessible spaces, is at least one a van accessible space?* : N_A (Rating: 0)

4. Are accessible spaces at least 2.4m wide with an access aisle at least 1.5m wide? Note: Two spaces may share an access aisle. : N_A (Rating: 0)

5. Are the access aisles marked to discourage parking in them? : N_A (Rating: 0)

6. Is the slope of the accessible parking spaces and access aisles no steeper than 1° in all directions? : N_A (Rating: 0)

7. Does the access aisle adjoin an accessible route? : N_A (Rating: 0)

8. Are accessible spaces identified with a sign that includes the International Symbol of Accessibility? Note: The International Symbol of Accessibility is not required on the ground. : N_A (Rating: 0)

9. Of the total parking spaces, are the accessible spaces located on the closest accessible route to the accessible entrance(s)? Note: If parking serves multiple entrances, accessible parking should be dispersed. : N_A (Rating: 0)

From : Camping area

To : Boat launch

Comments/Description : There are no stairs

2. What is the condition of the surface along this route? : Moderate (Rating: 1)

4. What is the type of surface? : Gravel

Clear Width

5. What is the typical route width (mm)? : More_than_1525 (Rating: 0)

Comments/Description : The route would be on the road

6. What is the narrowest route width (mm)? : More_than_1525 (Rating: 0)

Comments/Description : The route would be on the road

Obstacles

7. If the route is concrete, asphalt or boardwalk, are there any obstacles that exceed 13mm from the surface? : N_A (Rating: 0)

8. If yes, are the obstacles at least 1220mm apart? : N_A (Rating: 0)

9. If the route is anything other than concrete, asphalt or boardwalk, are there any obstacles that exceed 25mm from the surface? : No (Rating: 0)

10. If yes, are the obstacles at least 1220mm apart? : N_A (Rating: 0)

Openings

11. Are there any gaps or grates present that have an opening greater than 13mm? : No (Rating: 0)

12. If gaps/grates are present, do they run perpendicular to the path of travel? : N_A (Rating: 0)

Running Slope

13. What is the typical running slope on the route? : Moderate_2_-_3 (Rating: 1)

14. What is the maximum running slope on the route? : Moderate_2_-_3 (Rating: 1)

Cross Slope

15. What is the typical cross slope on the route? : Moderate_2_-_3 (Rating: 1)

16. What is the maximum cross slope on the route? : Moderate_2_-_3 (Rating: 1)

Resting Intervals

17. Are there resting intervals at the top and bottom of a route where the grade exceeds 3°? : N_A (Rating: 0)

18. If the running slope is greater than 3°, are there resting intervals in the middle of the route when the length exceeds 9.1m? : N_A (Rating: 0)

Protruding Objects

19. Is there a minimum of 2030mm vertical clearance for users to safely pass along the route without coming into contact with overhanging obstacles? : No_-_below_standard (Rating: 0)

20. Is there a minimum of 100mm horizontal clearance for users to safely pass along the route without

coming into contact with side obstacles? : Yes __meets_standard (Rating: 1)

Benches

21. Are there any benches along the route? : No (Rating: 0)

22. If yes, are the benches located approximately every 61m? : N_A (Rating: 0)

23. Is the bench seat height between 485mm - 510mm? : N_A (Rating: 0)

Ramps

24. Is there is a ramp? : No (Rating: 0)

25. Is the ramp at least 915mm wide?

Note: If there are handrails, measure between the handrails. : N_A (Rating: 0)

26. Is the surface stable, firm and slip resistant? : N_A (Rating: 0)

27. For each section of the ramp, is the running slope no greater than 5°?

Note: Rises no greater than 76mm with a slope no steeper than 7° and rises no greater than 150mm with a slope no steeper than 6° are permitted when due to space limitations. : N_A (Rating: 0)

28. Is there a level landing that is at least 1525mm long and at least as wide as the ramp: At the top of the ramp? : N_A (Rating: 0)

29. At the bottom of the ramp? : N_A (Rating: 0)

30. Is there a level landing where the ramp changes direction that is at least 1525mm x 1525mm? : N_A (Rating: 0)

31. If the ramp has a rise higher than 150mm are there handrails on both sides? : N_A (Rating: 0)

32. Is the top of the handrail gripping surface no less than 865mm and no greater than 965mm above the ramp surface? : N_A (Rating: 0)

33. Is the handrail gripping surface continuous and not obstructed along the top or sides? : N_A (Rating: 0)

34. If there are obstructions, is the bottom of the gripping surface obstructed no more than 20%? : N_A (Rating: 0)

Stairs

35. Are there floors or surfaces connected only by stairs, not an elevator or ramp? : No (Rating: 0)

36. How many flights of stairs are there? : N_A

37. If there are less than a flight, how many stairs are there? : N_A

38. Do all stair treads have a horizontal strip at the edge that is: 40mm-60mm deep, colour contrasted & extends the full width of the step? : N_A (Rating: 0)

- 39. If the stairs are not enclosed, is there a tactile warning system present at the landing of entrance to stairs system? : N_A (Rating: 0)**
- 40. Are there handrails on both sides of the stairs at a uniform height of 860mm-920mm above the front step? : N_A (Rating: 0)**
- 41. Do the handrails extend horizontally at the top and bottom of each flight of stairs? : N_A (Rating: 0)**
- 42. Are the handrails continuous around landings? : N_A (Rating: 0)**
- 43. Are the handrails continuously graspable, without interruption by vertical supports, newel posts, or other construction elements which require repositioning the hands while ascending or descending? : N_A (Rating: 0)**
- 44. Do the handrails have a graspable cross-section that is either circular with an outside diameter of 30mm-40mm or elliptical with an outside perimeter of 100mm-125mm? : N_A (Rating: 0)**

Comments/Description : The water is quite shallow close to shore

2. What type of surface is the beach area? : Grass

Comments/Description : a mix of sand and gravel

Comments/Description : There are no drop offs at the beach/picnic area, but there is a barrier at the boat launch so a wheel chair would have a difficult time accessing the picnic area

Comments/Description : There is a clear route to the water via the boat launch but not exactly the beach area

Dock/Fishing Platform

- 1. Is there a dock or fishing platform? : No (Rating: 0)**
- 2. For each section of the gangway, is the running slope no greater than 5°? : N_A (Rating: 0)**
- 3. Is the gangway at least 9.1m long? : N_A (Rating: 0)**
- 4. If a transition plate is steeper than 3°, is there a landing at the end of the transition plate? : N_A (Rating: 0)**
- 5. Are there any gaps or grates present that have an opening greater than 13mm? : N_A (Rating: 0)**
- 6. If gaps/grates are present, do they run perpendicular to the path of travel? : N_A (Rating: 0)**
- 7. If there are railings/guards/handrails on the dock/fishing platform, are at least 25% accessible with no more than 865mm above the ground or deck? : N_A (Rating: 0)**
- 8. Are the accessible railings dispersed throughout the dock/fishing platform? : N_A (Rating: 0)**
- 9. Is there a clear space at least 1220mm long x 760mm wide at the accessible railing? : N_A (Rating: 0)**
- 10. Is there a curb or barrier extending 51mm minimum above the surface of the dock/fishing platform? : N_A (Rating: 0)**

11. If there are no railings, is there a clear space at least 1220mm long x 760mm wide on the dock/fishing platform surface? : N_A (Rating: 0)

12. Is there a clear space for a person in a wheelchair to turn around, i.e. a circle at least 1525mm in diameter? : N_A (Rating: 0)

Comments/Description : Non motorized water craft only

**Measurement
(angle °) : 5**

Comments/Description : The slope is moderate as the water is shallow close to shore

4. What type of surface is the boat launch? : Dirt

Comments/Description : There are no accessible tables as the access to the picnic / tent area would be difficult for a person in a wheel chair

2. How many accessible picnic tables are there? : N_A

3. If the picnic table is up to 2.7m long, is there one wheelchair seating space? : N_A (Rating: 0)

4. If the picnic table is longer than 2.7m, are there at least two wheelchair spaces provided? : N_A (Rating: 0)

5. Is there clear and level ground space, 915mm measured from back edge of seats/benches? : N_A (Rating: 0)

6. Do the accessible spaces have adequate knee clearance, 685mm high x 760mm wide x 430mm deep? : N_A (Rating: 0)

7. Is the ground surface surrounding the accessible picnic table firm and stable? : N_A (Rating: 0)

8. Is there a clear, level accessible route to the picnic table? : N_A (Rating: 0)

Shelters

1. Are there any camp shelters? : No (Rating: 0)

2. What is the slope at the entrance to the camp shelter? : N_A (Rating: 0)

3. What type of surface is in the camp shelter? : N_A

4. Is the shelter surface firm and stable? : N_A (Rating: 0)

5. Is there a clear, level accessible route to the camp shelter? : N_A (Rating: 0)

Benches

1. Are any benches provided? : No (Rating: 0)

Recommendations : Benches would be awesome

2. If yes, how many benches are there? : N_A

3. Is the bench seat height between 485mm - 510mm? : N_A (Rating: 0)

4. Is there a minimum of 915mm x 1220mm clear ground space beside the bench? : N_A (Rating: 0)

5. Is there a clear, level accessible route to the bench? : N_A (Rating: 0)

**Measurement
(mm) : 990**

Comments/Description : bear-proof receptacle

4. If there are operable parts, can they be operated using one hand, without tightly grasping, pinching, or twisting the wrist and with no more than 2.3kg of force? : No (Rating: 0)

Comments/Description : 4 kg force

2. Is there a minimum of 1220mm clear ground space on all sides? : N_A (Rating: 0)

Comments/Description : Some fire pits are a circle of rocks, some picnic tables do not have fire pits

4. Is the grill height between 380mm - 865mm above the ground? : N_A (Rating: 0)

Comments/Description : no grill

5. Is the fire building surface height at least 230mm above the ground? : N_A (Rating: 0)

6. If there is a raised edge or wall around the fire building area, is the thickness less than 255mm? : N_A (Rating: 0)

7. Is there a clear, level accessible route to the campfire area? : N_A (Rating: 0)

Playground

1. Is there a playground? : No (Rating: 0)

2 What type of surface is in the play area? : N_A

3. Is the play area surface firm and stable? : N_A (Rating: 0)

4. Are any of the playground components accessible to wheelchair users? If yes, please describe. : N_A (Rating: 0)

5. Is there a clear, level accessible route to the playground? : N_A (Rating: 0)

1. Is there water access in separate areas at the site? : No

2. Are there any trails commencing from water access? : No

3. Are any public washrooms located at water access? : No

Goods and Services