

Mt Robson Visitors Centre ▼

Information

Date of Audit: 2016-08-30

Park Name: Barkerville Cemetary Trail

Key Features: Trails

Location: Cariboo, Quesnel, Cariboo Chilcotin Coast - Regional : Heritage Site (Lakes and Trails Circle Route)

Description:

Parking

**2. Are an adequate number of accessible spaces provided? :** N\_A (Rating: 0)

**3. Of the accessible spaces, is at least one a van accessible space?\* :** N\_A (Rating: 0)

**4. Are accessible spaces at least 2.4m wide with an access aisle at least 1.5m wide? Note: Two spaces may share an access aisle. :** N\_A (Rating: 0)

**5. Are the access aisles marked to discourage parking in them? :** N\_A (Rating: 0)

**6. Is the slope of the accessible parking spaces and access aisles no steeper than 1Â° in all directions? :** N\_A (Rating: 0)

**7. Does the access aisle adjoin an accessible route? :** N\_A (Rating: 0)

**8. Are accessible spaces identified with a sign that includes the International Symbol of Accessibility? Note: The International Symbol of Accessibility is not required on the ground. :** N\_A (Rating: 0)

**9. Of the total parking spaces, are the accessible spaces located on the closest accessible route to the accessible entrance(s)? Note: If parking serves multiple entrances, accessible parking should be dispersed. :** N\_A (Rating: 0)

Access Routes

Trails

Date of Audit : 2016-08-30

Name of Trail : Cemetery Ditch Trail

Section of trail audited : entire trail

Weather condition during audit : Sunny

Clear Width

**5. What is the typical trail width (mm)? :** More\_than\_1525 (Rating: 0)

**6. What is the narrowest trail width (mm)? :** More\_than\_1525 (Rating: 0)

Obstacles

**7. If the trail is concrete, asphalt or boardwalk, are there any obstacles that exceed 13mm from the surface? :** N\_A (Rating: 0)

**8. If yes, are the obstacles at least 1220mm apart? : N\_A (Rating: 0)**

**9. If the trail is anything other than concrete, asphalt or boardwalk, are there any obstacles that exceed 25mm from the surface? : No (Rating: 0)**

**10. If yes, are the obstacles at least 1220mm apart? : N\_A (Rating: 0)**

### **Openings**

**11. Are there any gaps or grates present that have an opening greater than 13mm? : No (Rating: 0)**

**12. If gaps/grates are present, do they run perpendicular to the path of travel? : N\_A (Rating: 0)**

### **Running Slope**

**13. What is the typical running slope on the trail? : Steep\_3\_-\_5 (Rating: 0)**

**14. What is the maximum running slope on the trail? : Steep\_3\_-\_5 (Rating: 0)**

**22. If yes, are the benches located approximately every 61m? : No\_-\_below\_standard (Rating: 0)**

**23. Is the bench seat height between 485mm - 510mm? : Yes\_-\_meets\_standard (Rating: 1)**

### **Ramps**

**24. Is there is a ramp? : No (Rating: 0)**

**25. Is the ramp at least 915mm wide?**

**Note: If there are handrails, measure between the handrails. : N\_A (Rating: 0)**

**26. Is the surface stable, firm and slip resistant? : N\_A (Rating: 0)**

**27. For each section of the ramp, is the running slope no greater than 5°?**

**Note: Rises no greater than 76mm with a slope no steeper than 7° and rises no greater than 150mm with a slope no steeper than 6° are permitted when due to space limitations. : N\_A (Rating: 0)**

**28. Is there a level landing that is at least 1525mm long and at least as wide as the ramp: At the top of the ramp? : N\_A (Rating: 0)**

**29. At the bottom of the ramp? : N\_A (Rating: 0)**

**30. Is there a level landing where the ramp changes direction that is at least 1525mm x 1525mm? : N\_A (Rating: 0)**

**31. If the ramp has a rise higher than 150mm are there handrails on both sides? : N\_A (Rating: 0)**

**32. Is the top of the handrail gripping surface no less than 865mm and no greater than 965mm above the ramp surface? : N\_A (Rating: 0)**

**33. Is the handrail gripping surface continuous and not obstructed along the top or sides? : N\_A (Rating: 0)**

**34. If there are obstructions, is the bottom of the gripping surface obstructed no more than 20%? : N\_A**  
(Rating: 0)

### Stairs

**35. Are there floors or surfaces connected only by stairs, not an elevator or ramp? : No** (Rating: 0)

**36. How many flights of stairs are there? : N\_A**

**37. If there are less than a flight, how many stairs are there? : N\_A**

**38. Do all stair treads have a horizontal strip at the edge that is: 40mm-60mm deep, colour contrasted & extends the full width of the step? : N\_A** (Rating: 0)

**39. If the stairs are not enclosed, is there a tactile warning system present at the landing of entrance to stairs system? : N\_A** (Rating: 0)

**40. Are there handrails on both sides of the stairs at a uniform height of 860mm-920mm above the front step? : N\_A** (Rating: 0)

**41. Do the handrails extend horizontally at the top and bottom of each flight of stairs? : N\_A** (Rating: 0)

**42. Are the handrails continuous around landings? : N\_A** (Rating: 0)

**43. Are the handrails continuously graspable, without interruption by vertical supports, newel posts, or other construction elements which require repositioning the hands while ascending or descending? : N\_A**  
(Rating: 0)

**44. Do the handrails have a graspable cross-section that is either circular with an outside diameter of 30mm-40mm or elliptical with an outside perimeter of 100mm-125mm? : N\_A** (Rating: 0)

### Viewing Area

**1. Is there a viewing area on the trail? : No** (Rating: 0)

**2. Is there sufficient clear ground space, a minimum of 915mm x 1220mm for the user to view the key features? : N\_A** (Rating: 0)

**3. Is the viewing area surface firm and stable? : N\_A** (Rating: 0)

**4. What type of surface is the viewing area? : N\_A**

**5. Is there a clear space between 815mm - 1320mm above the ground, free of obstructions and extending the full width of clear space? : N\_A** (Rating: 0)

### Picnic Area

**1. Are picnic tables provided? : No** (Rating: 0)

**2. How many accessible picnic tables are there? : N\_A**

**3. If the picnic table is up to 2.7m long, is there one wheelchair seating space? : N\_A** (Rating: 0)

**4. If the picnic table is longer than 2.7m, are there at least two wheelchair spaces provided? : N\_A (Rating: 0)**

**5. Is there clear and level ground space, 915mm measured from back edge of seats/benches? : N\_A (Rating: 0)**

**6. Do the accessible spaces have adequate knee clearance, 685mm high x 760mm wide x 430mm deep? : N\_A (Rating: 0)**

**7. Is the ground surface surrounding the accessible picnic table firm and stable? : N\_A (Rating: 0)**

**8. Is there a clear, level accessible route to the picnic table? : N\_A (Rating: 0)**

### **Shelters**

**1. Are there any camp shelters? : No (Rating: 0)**

**2. What is the slope at the entrance to the camp shelter? : N\_A (Rating: 0)**

**3. What type of surface is in the camp shelter? : N\_A**

**4. Is the shelter surface firm and stable? : N\_A (Rating: 0)**

**5. Is there a clear, level accessible route to the camp shelter? : N\_A (Rating: 0)**

### **Benches**

**1. Are any benches provided? : No (Rating: 0)**

**2. If yes, how many benches are there? : N\_A**

**3. Is the bench seat height between 485mm - 510mm? : N\_A (Rating: 0)**

**4. Is there a minimum of 915mm x 1220mm clear ground space beside the bench? : N\_A (Rating: 0)**

**5. Is there a clear, level accessible route to the bench? : N\_A (Rating: 0)**

### **Trash & Recycling Receptacles**

**1. Are there any trash &/or recycling receptacles? : No (Rating: 0)**

**2. Is the approach to the receptacle level, with no-step? : N\_A (Rating: 0)**

**3. If there are operable parts, is their height between 380mm - 1220mm above the ground? : N\_A (Rating: 0)**

**4. If there are operable parts, can they be operated using one hand, without tightly grasping, pinching, or twisting the wrist and with no more than 2.3kg of force? : N\_A (Rating: 0)**

**5. Is there a clear, level accessible route to the trash/recycling receptacle? : N\_A (Rating: 0)**

### **Campfires & Grills**

**1. Is there an area for campfires? : No (Rating: 0)**

- 2. Is there a minimum of 1220mm clear ground space on all sides? : N\_A (Rating: 0)**
- 3. Is the slope 3° or less in all directions? : N\_A (Rating: 0)**
- 4. Is the grill height between 380mm - 865mm above the ground? : N\_A (Rating: 0)**
- 5. Is the fire building surface height at least 230mm above the ground? : N\_A (Rating: 0)**
- 6. If there is a raised edge or wall around the fire building area, is the thickness less than 255mm? : N\_A (Rating: 0)**
- 7. Is there a clear, level accessible route to the campfire area? : No (Rating: 0)**
- 1. Are any public washrooms located at the trail head or on the trail? : No**

Washrooms

Camping

Water Access

Goods and Services