

Mt Robson Visitors Centre ▼

Information

Date of Audit: 2016-08-10

Park Name: Carp Lake Campground

Key Features: Camping, Beach, Fishing

Location: Fraser Fort George, Mackenzie, Northern BC - Provincial : Campground (Great Northern Circle Route)

Description: Two hours north of Prince George

Parking

Access Routes

From: : Road

To: : Accessible washroom

2. What is the condition of the surface along this route? : Good

4. What is the type of surface? : Boardwalk

Clear Width

5. What is the typical route width (mm)? : More_than_1525 (Rating: 0)

6. What is the narrowest route width (mm)? : between_1525_-_1220

Obstacles

7. If the route is concrete, asphalt or boardwalk, are there any obstacles that exceed 13mm from the surface? : No (Rating: 0)

8. If yes, are the obstacles at least 1220mm apart? : N_A (Rating: 0)

Comments/Description : Pavers set in gravel at the start

Recommendations : maintain gravel so that it is packed and flush

Improvement Priority : Med

Estimated Cost : Low

Openings

11. Are there any gaps or grates present that have an opening greater than 13mm? : No (Rating: 0)

12. If gaps/grates are present, do they run perpendicular to the path of travel? : N_A (Rating: 0)

Running Slope

13. What is the typical running slope on the route? : Flat_Gentle_1_or_less

14. What is the maximum running slope on the route? : Flat_Gentle_1_or_less

Cross Slope

15. What is the typical cross slope on the route? : Flat_Gentle_1_or_less

16. What is the maximum cross slope on the route? : Flat_Gentle_1_or_less

Resting Intervals

17. Are there resting intervals at the top and bottom of a route where the grade exceeds 3°? : N_A (Rating: 0)

18. If the running slope is greater than 3°, are there resting intervals in the middle of the route when the length exceeds 9.1m? : N_A (Rating: 0)

Protruding Objects

19. Is there a minimum of 2030mm vertical clearance for users to safely pass along the route without coming into contact with overhanging obstacles? : Yes_-_meets_standard (Rating: 1)

Comments/Description : some judicious pruning of the evergreens may be needed soon

Recommendations : check clearances and prune as needed to eliminate over hanging branches

Improvement Priority : Med

Estimated Cost : Low

Comments/Description : There is a curb on the sides of the boardwalk

Benches

21. Are there any benches along the route? : No (Rating: 0)

22. If yes, are the benches located approximately every 61m? : N_A (Rating: 0)

23. Is the bench seat height between 485mm - 510mm? : N_A (Rating: 0)

Ramps

24. Is there is a ramp? : No (Rating: 0)

25. Is the ramp at least 915mm wide?

Note: If there are handrails, measure between the handrails. : N_A (Rating: 0)

26. Is the surface stable, firm and slip resistant? : N_A (Rating: 0)

27. For each section of the ramp, is the running slope no greater than 5°?

Note: Rises no greater than 76mm with a slope no steeper than 7° and rises no greater than 150mm with a slope no steeper than 6° are permitted when due to space limitations. : N_A (Rating: 0)

28. Is there a level landing that is at least 1525mm long and at least as wide as the ramp: At the top of the ramp? : N_A (Rating: 0)

29. At the bottom of the ramp? : N_A (Rating: 0)

30. Is there a level landing where the ramp changes direction that is at least 1525mm x 1525mm? : N_A (Rating: 0)

31. If the ramp has a rise higher than 150mm are there handrails on both sides? : N_A (Rating: 0)

32. Is the top of the handrail gripping surface no less than 865mm and no greater than 965mm above the ramp surface? : N_A (Rating: 0)

33. Is the handrail gripping surface continuous and not obstructed along the top or sides? : N_A (Rating: 0)

34. If there are obstructions, is the bottom of the gripping surface obstructed no more than 20%? : N_A (Rating: 0)

Stairs

35. Are there floors or surfaces connected only by stairs, not an elevator or ramp? : No (Rating: 0)

36. How many flights of stairs are there? : N_A

37. If there are less than a flight, how many stairs are there? : N_A

38. Do all stair treads have a horizontal strip at the edge that is: 40mm-60mm deep, colour contrasted & extends the full width of the step? : N_A (Rating: 0)

39. If the stairs are not enclosed, is there a tactile warning system present at the landing of entrance to stairs system? : N_A (Rating: 0)

40. Are there handrails on both sides of the stairs at a uniform height of 860mm-920mm above the front step? : N_A (Rating: 0)

41. Do the handrails extend horizontally at the top and bottom of each flight of stairs? : N_A (Rating: 0)

42. Are the handrails continuous around landings? : N_A (Rating: 0)

43. Are the handrails continuously graspable, without interruption by vertical supports, newel posts, or other construction elements which require repositioning the hands while ascending or descending? : N_A (Rating: 0)

44. Do the handrails have a graspable cross-section that is either circular with an outside diameter of 30mm-40mm or elliptical with an outside perimeter of 100mm-125mm? : N_A (Rating: 0)

Trails

Washrooms

Date of Audit : 2016-08-11

Auditors Names : Cathy and Tamra

Weather condition during audit : Sunny

Washroom # : 1

Description of washroom location : Across from the picnic shelter

Type of Washroom : Out-house



1. If washrooms are available to the public, is at least one washroom designated as accessible? (Either one for each sex, or one unisex.) : Yes (Rating: 1)

Directional signage

2. Are there signs at inaccessible washrooms that give directions to accessible washrooms? : No (Rating: 0)

3. Is there an accessible route to the accessible washroom? : Yes (Rating: 1)

Comments/Description : boardwalk

4. If not all washrooms are accessible, is there a sign at the accessible washroom with the International Symbol of Accessibility? : Yes (Rating: 1)

5. Do text characters contrast with their backgrounds? : Yes (Rating: 1)

6. Are text characters raised? : No (Rating: 0)

7. Is there Braille? : No (Rating: 0)

8. Is the sign mounted on the wall, on latch side of the door?

Note: Signs are permitted on the push side of doors with closers and without hold-open devices. : No (Rating: 0)

9. So the baseline of the lowest character is at least 1220mm above the floor and the baseline of the highest character is no more than 1525mm above the floor?

Note: If the sign is at double doors with one active leaf, the sign should be on the inactive leaf; if both leaves are active, the sign should be on the wall to the right of the right leaf. : Yes (Rating: 1)

Measurement (mm) : 1400

Interior doors

10. Is the door opening width at least 815mm clear, between the face of the door and the stop, when the door is open 90°? : Yes (Rating: 1)

**Measurement
(mm) : 900**

11. If there is a front approach to the pull side of the door, is there at least 455mm of maneuvering clearance beyond the latch side plus at least 1525mm clear depth? : Yes (Rating: 1)

**Measurement
(mm) w x d : 1470 x 1660**

12. On both sides of the door, is the floor surface of the maneuvering clearance level (no steeper than 1°)? : Yes (Rating: 1)

**Measurement
(angle °) : 0**

13. If the threshold is vertical is it no more than 6mm high?

Or : Yes (Rating: 1)

**Measurement
(mm) : 5**

14. If the threshold is beveled, is it no more than 19mm high? : N_A (Rating: 0)

15. Is the door equipped with hardware that is operable with one hand and does not require tight grasping, pinching or twisting of the wrist? : Yes (Rating: 1)

**Measurement
(mm) : 900**

17. Can the door be opened easily, maximum 2.3kg of force?

Note: You can use a pressure gauge or fish scale to measure force. : Yes (Rating: 1)

**Measurement
(kg) : 1**

18. If the door has a closer, does it take at least 5 seconds to close from open position of 90° to a position of 12° from the latch? : N_A (Rating: 0)

19. If there are two doors in a series, e.g. vestibule, is the distance between the doors at least 1220mm plus the width of the doors when swinging into the space? : N_A (Rating: 0)

20. If there is a privacy wall and the door swings out, is there at least 610mm of maneuvering clearance beyond the door latch side and 1065mm to the privacy wall? : N_A (Rating: 0)

21. If there is a privacy wall and the door swings in, is there at least 610mm of maneuvering clearance beyond the door latch side and at least 1220mm to the privacy wall if there is no door closer or at least 1370mm if there is a door closer? : N_A (Rating: 0)

22. In a unisex washroom if the door swings in and over a clear floor space at an accessible fixture, is there

a clear floor space at least 760mm x 1220mm beyond the swing of the door? : N_A (Rating: 0)

Toilet stall

23. Is there an individual accessible toilet stall? : Yes (Rating: 1)

24. Is the stall door opening width at least 815mm clear, between the face of the door and the stop, when the door is open 90°? : Yes (Rating: 1)

Measurement

(mm) : 900

25. If there is a front approach to the pull side of the stall door, is there at least 455mm of maneuvering clearance beyond the latch side plus 1525mm clear depth? : Yes (Rating: 1)

Clearance

(mm) : 1660

Depth

(mm) : 1400

26. Is the door self-closing? : No (Rating: 0)

27. Are there door pulls on both sides of the door that are operable with one hand and do not require tight grasping pinching or twisting of the wrist?* : Yes (Rating: 1)

28. Is the lock operable with one hand and without tight grasping, pinching or twisting of the wrist? : Yes (Rating: 1)

29. Are the operable parts of the door hardware mounted no less than 865mm and no greater than 1220mm above the floor? : Yes (Rating: 1)

Measurement

(mm) : 900

30. Is the stall at least 1525mm wide? : Yes (Rating: 1)

Measurement

(mm) : 1610

31. If the toilet is wall hung, is the stall at least 1420mm deep?

Or : N_A (Rating: 0)

Measurement

(mm) : 1630

32. If the toilet is floor mounted, is the stall at least 1500mm deep? : Yes (Rating: 1)

Measurement

(mm) : 1630

If the door swings in, is the stall area beyond the swing of the door:

33. A minimum of 1525mm wide x 1420mm deep for wall hung toilet?

Or : N_A (Rating: 0)

34. A minimum of 1525mm wide x 1500mm deep for floor mounted toilet? : Yes (Rating: 1)

Measurement

(mm x mm) : 1610 x 1630

Toilet

35. Is the centerline of the toilet no less than 405mm and no greater than 455mm from the side wall or partition? : No (Rating: 0)

Measurement

(mm) : 375

36. Is clearance provided around the toilet measuring at least 1525mm from the side wall and at least 1420mm from the rear wall? : Yes (Rating: 1)

From side wall

(mm) : 1610

From rear wall

(mm) : 1630

37. Is the height of the toilet no less than 430mm and no greater than 485mm above the floor measured to the top of the seat? : No (Rating: 0)

Measurement

(mm) : 390

Grab bars

38. Is there a grab bar at least 1065mm long on the side wall? : No (Rating: 0)

Measurement

(mm) : 580

Recommendations : install grab bar that meets or exceeds standard

Improvement Priority : Med

Estimated Cost : Low

39. Is it located no more than 305mm from the rear wall? : No (Rating: 0)

Measurement

(mm) : 610

41. Is it mounted no less than 840mm and no greater than 915mm above the floor to the top of the gripping surface? : Yes (Rating: 1)

Measurement

(mm) : 900

42. Is there at least 305mm clearance between the grab bar and protruding objects above? : N_A (Rating: 0)

43. Is there at least 38mm clearance between the grab bar and projecting objects below? : Yes (Rating: 1)

Measurement

(mm) : 125

44. Is the space between the wall and the grab bar 38mm : Yes (Rating: 1)

Measurement

(mm) : 50

45. Is there a grab bar at least 915mm long on the rear wall? : No (Rating: 0)

Comments/Description : no grab bar

Recommendations : install grab bar that meets or exceeds standard

46. Does the grab bar extend at least 305mm from the centerline of the toilet on one side (side wall)? : N_A (Rating: 0)

47. Does the grab bar extend at least 610mm on the other (open) side? : N_A (Rating: 0)

48. Is the grab bar mounted no less than 840mm and no greater than 915mm above the floor to the top of the gripping surface? : N_A (Rating: 0)

49. Are there at least 305mm clearance between the grab bar and protruding objects above? : N_A (Rating: 0)

50. Are there at least 38mm clearance between the grab bar and projecting objects below? : N_A (Rating: 0)

51. Is the space between the wall and the grab bar 38mm inches? : N_A (Rating: 0)

Toilet flush controls

52. If the flush control is hand operated, is the operable part located no higher than 1220mm above the floor? : N_A (Rating: 0)

53. If the flush control is hand operated, can it be operated with one hand and without tight grasping, pinching, or twisting of the wrist? : N_A (Rating: 0)

54. Is the force required to activate the flush control no greater than 2.3kg? : N_A (Rating: 0)

55. Is the flush control on the open side of the toilet? : N_A (Rating: 0)

Toilet paper dispenser

56. Is the toilet paper dispenser located no less than 180mm and no greater than 230mm from the front of the toilet to the center line of the dispenser? : No (Rating: 0)

**Measurement
(mm) : 170**

57. Is the outlet of the dispenser: Located no less than 380mm and no greater than 1220mm above the floor? : Yes (Rating: 1)

**Measurement
(mm) : 690**

58. Is the dispenser located behind grab bars? : No (Rating: 0)

59. Does the dispenser allow continuous paper flow? : Yes (Rating: 1)

Sink

60. Does at least one sink have a clear floor space for a forward approach at least 760mm wide and 1220mm long? : N_A (Rating: 0)

61. Do no less than 430mm and no greater than 635mm of the clear floor space extend under the sink so that a person using a wheelchair can get close enough to reach the faucet? : N_A (Rating: 0)

62. Is the front of the sink or counter surface, whichever is higher, no more than 865mm above the floor? : N_A (Rating: 0)

63. Is there at least 685mm height clearance from the floor to the bottom of the sink that extends at least 205mm deep under the sink for knee clearance? : N_A (Rating: 0)

64. Is there toe clearance at least 230mm high?

Note: Space extending greater than 150mm beyond the available toe clearance at 230mm above the floor is not considered toe clearance. : N_A (Rating: 0)

65. Are pipes below the sink insulated or otherwise configured to protect against contact? : N_A (Rating: 0)

66. Can the faucet be operated without tight grasping, pinching, or twisting of the wrist? : N_A (Rating: 0)

67. Is the force required to activate the faucet no greater than 2.3 kg? : N_A (Rating: 0)

Washroom fixtures

68. Is there a clear path to at least one of each type of fixture, e.g. sink, hand dryer, garbage bin etc., that is at least 915mm wide? : N_A (Rating: 0)

69. Is there clear floor space available for a person in a wheelchair to turn around, i.e. a circle at least 1525mm in diameter or a T-shaped space within a 1525mm square? : N_A (Rating: 0)

Mirror

70. If the mirror is over a sink or countertop, is the bottom edge of the reflecting surface no higher than 1015mm above the floor?

Or : N_A (Rating: 0)

71. If the mirror is not over the sink or countertop, is the bottom edge of the reflecting surface no higher than 890mm above the floor? : N_A (Rating: 0)

Coat hook

72. If there is a coat hook, is it no less than 380mm and no greater than 1220mm above the floor?* : N_A (Rating: 0)

Soap dispenser

Are the operable parts of the soap dispenser within one of the following reach ranges:

73. Above sinks or counters no less than 510mm and no greater than 635mm deep: no higher than 1120mm above the floor?

Or : N_A (Rating: 0)

74. Above sinks less than 510mm deep: no higher than 1220mm above the floor?

Or : N_A (Rating: 0)

75. Not over an obstruction: no higher than 1220mm above the floor? : N_A (Rating: 0)

Hand dryer/Towel dispenser

Are the operable parts of the hand dryer or towel dispenser within one of the following reach ranges:

76. Above sinks or counters no less than 510mm and no greater than 635mm deep: no higher than 1120mm above the floor?

Or : N_A (Rating: 0)

77. Above sinks less than 510mm deep: no higher than 1220mm above the floor?

Or : N_A (Rating: 0)

78. Not over an obstruction: no higher than 1220mm above the floor? : N_A (Rating: 0)

79. Can the operable parts of the hand dryer or towel dispenser be operated without tight grasping, pinching or twisting of the wrist? : N_A (Rating: 0)

80. Is the force required to activate the hand dryer or towel dispenser no greater than 2.3kg? : N_A (Rating: 0)

Controls - light switches

81. Is there a clear floor space at least 760mm wide by at least 1220mm long for a forward or parallel approach? : N_A (Rating: 0)

82. Are the operable parts no higher than 1220mm above the floor? : N_A (Rating: 0)

83. Can the control be operated with one hand and without tight grasping, pinching, or twisting of the wrist? : N_A (Rating: 0)

Additional comments regarding assessment: : This is generally a very good accessible outhouse. The access route is smooth level and gentle with minimal slope and plenty of room to maneuver. It is well signed to eliminate guess work. The grab bars need to be replaced with longer horizontal ones to maximize the range of users. In an ideal world it would be nice to see two more of these on either end of the camp ground.

Suggestions for improvement of audit tool: : I would like the access route incorporated into the washroom check list to ensure it goes with the right one and gets done. Also I think that outhouses need a separate check list OR when you pick the outhouse button at the start the items that are normally not present are auto filled.



Description of Photo 1 : Bit of a bump at the start of the access route



Description of Photo 2 : Signage was good, could have used a directional one at the standard outhouses



Description of Photo 3 : Wide enough, note the curb to catch a white cane



Description of Photo 4 : Lots of maneuvering room

Camping

Date of Audit (YYYY-MM-DD) : 2016-08-10

Name of Campground : Carp Lake Campground

Location of Campsite : on Kettle Bay on Carp Lake, 32 kms off Highway 97 at McLeod Lake

Weather condition during audit : Sunny



1. Does the number of accessible camp sites comply with the table above? : N_A (Rating: 0)

Comments/Description : 90 sites, none of which are officially labeled accessible

Campsite

2. Is the camp site surface firm and stable? : Yes (Rating: 1)

3. What type of surface is in the campsite? : Gravel

4. Is the accessible campsite at least 4.9m wide?

Or : Yes_ - _Meets_Standard (Rating: 1)

Measurement

(m) : 5

Comments/Description : average width is 5 meters

5. If it is an RV site, is the parking area at least 6m wide? : Yes_ - _Meets_Standard (Rating: 1)

Measurement

(m) : 6

Comments/Description : some sites, usually the doubles, met or exceeded the width

6. If the campsite surface is concrete or asphalt, is the slope 1° or less? : N_A (Rating: 0)

7. If the campsite surface is anything other than concrete & asphalt, is the slope 3° or less? : Yes_ - _Meets_Standard (Rating: 1)

Tent Pads/Platforms

8. Is there a minimum of 1220mm clear space on all sides surrounding the tent pad or platform? : Yes_ - _Meets_Standard (Rating: 1)

Measurement

(mm) : 1500

Comments/Description : 7 meters by 4 meters from the edge of the table, no designated tent pad

9. What type of surface is the tent pad/ platform? : Gravel

10. What is the slope of the tent pad/ platform? : Flat_Gentle_1_or_less

11. Is there an accessible entrance or ramp on to the tent pad/platform? : N_A (Rating: 0)

Comments/Description : no designated or separated tent pad, just a flat site

Utility & Sewage Hook Ups

12. Is there sufficient clear ground space, a minimum of 1220mm x 1525mm surrounding the hook ups? : N_A (Rating: 0)

Comments/Description : no hook ups at any sites but there is a sani-station at the entrance

13. If there are operable parts, can they be operated using one hand, without tightly grasping, pinching, or twisting the wrist and with no more than 2.3kg of force? : N_A (Rating: 0)

Campfires & Grills

14. Is there an area for campfires? : Yes (Rating: 1)

Comments/Description : some sites had grills that could be adjusted for height

15. Is there a minimum of 1220mm clear ground space on all sides? : Yes_-_Meets_Standard (Rating: 1)

**Measurement
(mm) :** 1900

16. Is the slope 3° or less in all directions? : Yes (Rating: 1)

**Measurement
(angle °) :** 2

17. Is the grill height between 380mm - 865mm above the ground? : No (Rating: 0)

Comments/Description : fixed grills were at 230 mm adjustable grills went from 240 to 500 mm

18. Is the fire building surface height at least 230mm above the ground? : No (Rating: 0)

**Measurement
(mm) :** 215

19. If there is a raised edge or wall around the fire building area, is the thickness less than 255mm? : No (Rating: 0)

**Measurement
(mm) :** 5

Comments/Description : thick metal ring

20. Is there a clear, level accessible route to the campfire area? : Yes (Rating: 1)

21. Are picnic tables provided? : Yes (Rating: 1)

22. How many accessible picnic tables are there? : over_10

Comments/Description : they are at all the double sites and some others. About 1/3 of the sites have the accessible table

23. If the picnic table is up to 2.7m long, is there one wheelchair seating space? : Yes (Rating: 1)

Comments/Description : 2170 mm long

24. If the picnic table is longer than 2.7m, are there at least two wheelchair spaces provided? : N_A (Rating: 0)**25. Is there clear and level ground space, 915mm measured from back edge of seats/benches? : Yes - _Exceeds_Standard**

Measurement (mm) : 1340

26. Do the accessible spaces have adequate knee clearance, 685mm high x 760mm wide x 430mm deep? : Yes (Rating: 1)

Measurement (mm) h x w x d : 810 x 745 x 400

27. Is the ground surface surrounding the accessible picnic table firm and stable? : Yes (Rating: 1)

Comments/Description : usually hard packed gravel

28. Is there a clear, level accessible route to the picnic table? : Yes (Rating: 1)**Water Taps****1. Are there any water taps? : Yes (Rating: 1)**

Comments/Description : see picture

2. Is there sufficient clear ground space, a minimum of 1829mm x 1220mm surrounding the water tap? : Yes - _Meets_Standard (Rating: 1)**3. Is the water spout height between 280mm - 305mm? : Yes (Rating: 1)****4. Is the height of operable parts (i.e. taps or levers) between 380mm - 1220mm above the ground? : Yes (Rating: 1)****5. If there are operable parts, can they be operated using one hand, without tightly grasping, pinching, or twisting the wrist and with no more than 2.3kg of force? : No (Rating: 0)**

Comments/Description : the spouts were an unusual design, difficult to figure out as we had never seen them before

6. Is there a clear, level accessible route to the water tap? : Yes (Rating: 1)

Comments/Description : sometimes across grass

Water Fountains

1. **Is there a water fountain?** : No (Rating: 0)
2. **Does it have a lever or push bar control on the front or both sides?** : N_A (Rating: 0)
3. **Is the spout opening height between 750mm - 915mm above the ground?** : N_A (Rating: 0)
4. **Is there a minimum width of 800mm clearance space directly in front of the water fountain?** : N_A (Rating: 0)
5. **Is there a clear, level accessible route to the water fountain?** : N_A (Rating: 0)

Trash & Recycling Receptacles

1. **Are there any trash &/or recycling receptacles?** : Yes (Rating: 1)
2. **Is the approach to the receptacle level, with no-step?** : Yes (Rating: 1)
3. **If there are operable parts, is their height between 380mm - 1220mm above the ground?** : Yes (Rating: 1)

Measurement (mm) : 920

4. **If there are operable parts, can they be operated using one hand, without tightly grasping, pinching, or twisting the wrist and with no more than 2.3kg of force?** : No (Rating: 0)

Comments/Description : bearproof

5. **Is there a clear, level accessible route to the trash/recycling receptacle?** : Yes (Rating: 1)

Shelters

1. **Are there any camp shelters?** : Yes (Rating: 1)
2. **What is the slope at the entrance to the camp shelter?** : Flat_Gentle_1_or_less
3. **What type of surface is in the camp shelter?** : Concrete

Comments/Description : outside is grass and gravel

4. **Is the shelter surface firm and stable?** : Yes (Rating: 1)
5. **Is there a clear, level accessible route to the camp shelter?** : Yes (Rating: 1)

Benches

1. **Are any benches provided?** : No (Rating: 0)
2. **If yes, how many benches are there?** : N_A
3. **Is the bench seat height between 485mm - 510mm?** : N_A (Rating: 0)

4. Is there a minimum of 915mm x 1220mm clear ground space beside the bench? : N_A (Rating: 0)

5. Is there a clear, level accessible route to the bench? : N_A (Rating: 0)

Playground

1. Is there a playground? : Yes (Rating: 1)

2 What type of surface is in the play area? : Sand

Comments/Description : sand was hard packed the day of the audit

Recommendations : consider replacing sand with accessible surface such as recycled rubber

Improvement Priority : Low

Estimated Cost : High

3. Is the play area surface firm and stable? : Yes (Rating: 1)

4. Are any of the playground components accessible to wheelchair users? If yes, please describe. : No (Rating: 0)

5. Is there a clear, level accessible route to the playground? : No (Rating: 0)

Comments/Description : across grass, lip around the play area ranges from 20 to 50 mm

Amphitheatre

1. Is there an amphitheatre? : No (Rating: 0)

Amphitheatre Seating

2. Are an adequate number of wheelchair spaces provided? : N_A (Rating: 0)

3. Are wheelchair spaces dispersed to allow location choices and viewing angles equivalent to other seating, including specialty seating areas that provide distinct services and amenities? : N_A (Rating: 0)

4. Where people are expected to remain seated, do people in wheelchair spaces have a clear line of sight over and between the heads of others in front of them? : N_A (Rating: 0)

5. Where people are expected to stand, do people in wheelchair spaces have a clear line of sight over and between the heads of others in front of them? : N_A (Rating: 0)

6. If there is a single wheelchair space, is it at least 915mm wide? : N_A (Rating: 0)

7. If there are two adjacent wheelchair spaces, are they each at least 840mm wide? : N_A (Rating: 0)

8. If the wheelchair space can be entered from the front or rear, is it at least 1220mm deep? : N_A (Rating: 0)

9. If the wheelchair space can only be entered from the side, is it at least 1525mm deep? : N_A (Rating: 0)

10. Do wheelchair spaces adjoin, but not overlap, accessible routes? : N_A (Rating: 0)

11. Is there at least one companion seat for each wheelchair space? : N_A (Rating: 0)

12. Is the companion seat located so the companion is shoulder-to-shoulder with the person in a wheelchair? : N_A (Rating: 0)

13. Is the companion seat equivalent in size, quality, comfort and amenities to seating in the immediate area? : N_A (Rating: 0)

2. Are there any public buildings (visitors centre/ interpretive centre/cafes etc) at the campground? : No (Rating: 0)

3. Are there any trails at the campground? : Yes - _TRAILS_checklist_must_also_be_completed (Rating: 0)

4. Is there a beach, dock/fishing platform or boat launch? : Yes - _WATER_ACCESS_checklist_must_also_be_completed (Rating: 0)

Additional comments regarding assessment: : The camping area is generally flat, gentle slope, the sites are generous in size. About a third of the tables are the extended accessible style, allowing a variety of choices for camping from view lots overlooking the lake to spots beside the playground. There is only one accessible outhouse for 90 sites, in the middle of the campground across from the picnic shelter. I hope there are plans to replace a couple of the outlying outhouses with the larger style where feasible.



Description of Photo 1 : The trail to the accessible outhouse from one of the campsites. There is a boardwalk from the road on the other side



Description of Photo 2 : It was a real pleasure to see these tables spotted all over the camp sites. We counted over 30 of them.



Description of Photo 3 : The adjustable grill provided at some sites looked very useful



Description of Photo 4 : Water tap needed directions to use

Water Access

Date of Audit : 2016-08-11

Body of water : Lake

Location : Carp Lake campground, near picnic shelter

Weather condition during audit : Sunny



Comments/Description : Beach access & trail commence in the campground near the picnic shelter

2. Are an adequate number of accessible spaces provided? : N_A (Rating: 0)

Total # : 32

Accessible # : 0

3. Of the accessible spaces, is at least one a van accessible space?* : N_A (Rating: 0)

4. Are accessible spaces at least 2.4m wide with an access aisle at least 1.5m wide? Note: Two spaces may share an access aisle. : N_A (Rating: 0)

5. Are the access aisles marked to discourage parking in them? : N_A (Rating: 0)

6. Is the slope of the accessible parking spaces and access aisles no steeper than 1° in all directions? : N_A (Rating: 0)

7. Does the access aisle adjoin an accessible route? : N_A (Rating: 0)

8. Are accessible spaces identified with a sign that includes the International Symbol of Accessibility? Note: The International Symbol of Accessibility is not required on the ground. : N_A (Rating: 0)

9. Of the total parking spaces, are the accessible spaces located on the closest accessible route to the accessible entrance(s)? Note: If parking serves multiple entrances, accessible parking should be dispersed.
: N_A (Rating: 0)

From: : Parking area

To: : Kettle Bay Beach

2. What is the condition of the surface along this route? : Moderate (Rating: 1)

4. What is the type of surface? : Gravel

Comments/Description : the stairs are concrete

Clear Width

5. What is the typical route width (mm)? : More_than_1525 (Rating: 0)

6. What is the narrowest route width (mm)? : More_than_1525 (Rating: 0)

Obstacles

7. If the route is concrete, asphalt or boardwalk, are there any obstacles that exceed 13mm from the surface? : No (Rating: 0)

8. If yes, are the obstacles at least 1220mm apart? : No (Rating: 0)

Openings

11. Are there any gaps or grates present that have an opening greater than 13mm? : No (Rating: 0)

12. If gaps/grates are present, do they run perpendicular to the path of travel? : No (Rating: 0)

Running Slope

13. What is the typical running slope on the route? : Very_steep_above_5 (Rating: 0)

Comments/Description : Steep stairs near the start of the trail, rest was not walked, described as narrow & for able bodied only

14. What is the maximum running slope on the route? : Very_steep_above_5 (Rating: 0)

16. What is the maximum cross slope on the route? : Moderate_2_-_3 (Rating: 1)

Resting Intervals

17. Are there resting intervals at the top and bottom of a route where the grade exceeds 3°? : No (Rating: 0)

18. If the running slope is greater than 3°, are there resting intervals in the middle of the route when the length exceeds 9.1m? : No (Rating: 0)

Protruding Objects

19. Is there a minimum of 2030mm vertical clearance for users to safely pass along the route without coming into contact with overhanging obstacles? : Yes _ _meets_ standard (Rating: 1)

Comments/Description : not able to evaluate

20. Is there a minimum of 100mm horizontal clearance for users to safely pass along the route without coming into contact with side obstacles? : Yes _ _meets_ standard (Rating: 1)

Comments/Description : not able to evaluate

Benches

21. Are there any benches along the route? : No (Rating: 0)

22. If yes, are the benches located approximately every 61m? : N_A (Rating: 0)

23. Is the bench seat height between 485mm - 510mm? : N_A (Rating: 0)

Ramps

24. Is there is a ramp? : No (Rating: 0)

25. Is the ramp at least 915mm wide?

Note: If there are handrails, measure between the handrails. : N_A (Rating: 0)

26. Is the surface stable, firm and slip resistant? : N_A (Rating: 0)

27. For each section of the ramp, is the running slope no greater than 5°?

Note: Rises no greater than 76mm with a slope no steeper than 7° and rises no greater than 150mm with a slope no steeper than 6° are permitted when due to space limitations. : N_A (Rating: 0)

28. Is there a level landing that is at least 1525mm long and at least as wide as the ramp: At the top of the ramp? : N_A (Rating: 0)

29. At the bottom of the ramp? : N_A (Rating: 0)

30. Is there a level landing where the ramp changes direction that is at least 1525mm x 1525mm? : N_A (Rating: 0)

31. If the ramp has a rise higher than 150mm are there handrails on both sides? : N_A (Rating: 0)

32. Is the top of the handrail gripping surface no less than 865mm and no greater than 965mm above the ramp surface? : N_A (Rating: 0)

33. Is the handrail gripping surface continuous and not obstructed along the top or sides? : N_A (Rating: 0)

34. If there are obstructions, is the bottom of the gripping surface obstructed no more than 20%? : N_A (Rating: 0)

36. How many flights of stairs are there? : 3

37. If there are less than a flight, how many stairs are there? : N_A

38. Do all stair treads have a horizontal strip at the edge that is: 40mm-60mm deep, colour contrasted & extends the full width of the step? : N_A (Rating: 0)

Comments/Description : see pictures

39. If the stairs are not enclosed, is there a tactile warning system present at the landing of entrance to stairs system? : No (Rating: 0)

40. Are there handrails on both sides of the stairs at a uniform height of 860mm-920mm above the front step? : No - Below Standard (Rating: 0)

Comments/Description : one side only, see pictures

41. Do the handrails extend horizontally at the top and bottom of each flight of stairs? : N_A (Rating: 0)

42. Are the handrails continuous around landings? : N_A (Rating: 0)

43. Are the handrails continuously graspable, without interruption by vertical supports, newel posts, or other construction elements which require repositioning the hands while ascending or descending? : N_A (Rating: 0)

Comments/Description : see pictures

44. Do the handrails have a graspable cross-section that is either circular with an outside diameter of 30mm-40mm or elliptical with an outside perimeter of 100mm-125mm? : N_A (Rating: 0)

2. What type of surface is the beach area? : Sand

Comments/Description : Pimarily sand in the swimming area changing to pebbles around the docks

Comments/Description : only able to observe from height

4. Is there a clear route to the water edge that is: at least 915mm wide, level and has a firm/stable surface? : No (Rating: 0)

Comments/Description : no accessible route to the waters edge suitable for a wheel chair

Comments/Description : no accessible for wheelchairs, see pictures

2. For each section of the gangway, is the running slope no greater than 5°? : N_A (Rating: 0)

3. Is the gangway at least 9.1m long? : N_A (Rating: 0)

4. If a transition plate is steeper than 3°, is there a landing at the end of the transition plate? : N_A (Rating: 0)

5. Are there any gaps or grates present that have an opening greater than 13mm? : N_A (Rating: 0)

6. If gaps/grates are present, do they run perpendicular to the path of travel? : N_A (Rating: 0)

7. If there are railings/guards/handrails on the dock/fishing platform, are at least 25% accessible with no more than 865mm above the ground or deck? : N_A (Rating: 0)

8. Are the accessible railings dispersed throughout the dock/fishing platform? : N_A (Rating: 0)

9. Is there a clear space at least 1220mm long x 760mm wide at the accessible railing? : N_A (Rating: 0)

10. Is there a curb or barrier extending 51mm minimum above the surface of the dock/fishing platform? : N_A (Rating: 0)

11. If there are no railings, is there a clear space at least 1220mm long x 760mm wide on the dock/fishing platform surface? : N_A (Rating: 0)

12. Is there a clear space for a person in a wheelchair to turn around, i.e. a circle at least 1525mm in diameter? : N_A (Rating: 0)

**Measurement
(angle °) : 5**

Comments/Description : n/a

**Measurement
(m) : 15**

Comments/Description : n/a

4. What type of surface is the boat launch? : N_A

Picnic Area

1. Are picnic tables provided? : No (Rating: 0)

2. How many accessible picnic tables are there? : N_A

3. If the picnic table is up to 2.7m long, is there one wheelchair seating space? : N_A (Rating: 0)

4. If the picnic table is longer than 2.7m, are there at least two wheelchair spaces provided? : N_A (Rating: 0)

5. Is there clear and level ground space, 915mm measured from back edge of seats/benches? : N_A (Rating: 0)

6. Do the accessible spaces have adequate knee clearance, 685mm high x 760mm wide x 430mm deep? : N_A (Rating: 0)

7. Is the ground surface surrounding the accessible picnic table firm and stable? : N_A (Rating: 0)

8. Is there a clear, level accessible route to the picnic table? : N_A (Rating: 0)

Shelters

1. Are there any camp shelters? : No (Rating: 0)

2. What is the slope at the entrance to the camp shelter? : N_A (Rating: 0)

3. What type of surface is in the camp shelter? : N_A

4. Is the shelter surface firm and stable? : N_A (Rating: 0)

5. Is there a clear, level accessible route to the camp shelter? : N_A (Rating: 0)

Benches

1. Are any benches provided? : No (Rating: 0)

2. If yes, how many benches are there? : N_A

4. Is there a minimum of 915mm x 1220mm clear ground space beside the bench? : N_A (Rating: 0)

5. Is there a clear, level accessible route to the bench? : N_A (Rating: 0)

Trash & Recycling Receptacles

1. Are there any trash &/or recycling receptacles? : No (Rating: 0)

Comments/Description : unable to confirm

2. Is the approach to the receptacle level, with no-step? : N_A (Rating: 0)

3. If there are operable parts, is their height between 380mm - 1220mm above the ground? : N_A (Rating: 0)

4. If there are operable parts, can they be operated using one hand, without tightly grasping, pinching, or twisting the wrist and with no more than 2.3kg of force? : N_A (Rating: 0)

5. Is there a clear, level accessible route to the trash/recycling receptacle? : N_A (Rating: 0)

Campfires & Grills

1. Is there an area for campfires? : No (Rating: 0)

2. Is there a minimum of 1220mm clear ground space on all sides? : N_A (Rating: 0)

3. Is the slope 3° or less in all directions? : N_A (Rating: 0)

4. Is the grill height between 380mm - 865mm above the ground? : N_A (Rating: 0)

5. Is the fire building surface height at least 230mm above the ground? : N_A (Rating: 0)

6. If there is a raised edge or wall around the fire building area, is the thickness less than 255mm? : N_A (Rating: 0)

7. Is there a clear, level accessible route to the campfire area? : N_A (Rating: 0)

Playground

1. Is there a playground? : No (Rating: 0)

2 What type of surface is in the play area? : N_A

3. Is the play area surface firm and stable? : N_A (Rating: 0)

4. Are any of the playground components accessible to wheelchair users? If yes, please describe. : N_A (Rating: 0)

5. Is there a clear, level accessible route to the playground? : N_A (Rating: 0)

1. Is there water access in separate areas at the site? : Yes_-
_ACCESS_ROUTE_checklist_must_also_be_completed

2. Are there any trails commencing from water access? : Yes_- _TRAILS_checklist_must_also_be_completed

3. Are any public washrooms located at water access? : No

Additional comments regarding assessment: : This campsite is located up on an escarpment so access to the beach & trail is down a long long set of steep stairs. The view from the top is excellent. If you are brave and agile this is the place for you to shine. Those of us with bad knees, wheels or other mobility issues will just enjoy the view up top. The beach at the boat launch is an alternative as it can be reached by a road.



Description of Photo 1 : Those who don't like heights may wish to pass



Description of Photo 2 : Looks like fun until you see the stairs. Then you decide.



Description of Photo 3 : Stairs to boat launch beach for campers above. They could also use the road down

Description of Photo 4 : Fish cleaning station with instructions to remove all waste and clean up afterwards.

Goods and Services