

Mt Robson Visitors Centre ▼

## Information

Date of Audit: 2016-08-17

Park Name: Ginter's Meadow

Key Features: Trails

Location: Fraser Fort George, Prince George, Northern BC - Municipal : Trail (Heritage Discovery Circle Route)

Description: primarily an off leash dog park

### Parking

**2. Are an adequate number of accessible spaces provided?** : Yes\_ \_Meets\_ Standard (Rating: 1)

**3. Of the accessible spaces, is at least one a van accessible space?\*** : Yes\_ \_Meets\_ Standard (Rating: 1)

**4. Are accessible spaces at least 2.4m wide with an access aisle at least 1.5m wide? Note: Two spaces may share an access aisle.** : Yes\_ \_Meets\_ Standard (Rating: 1)

**5. Are the access aisles marked to discourage parking in them?** : N\_A (Rating: 0)

**6. Is the slope of the accessible parking spaces and access aisles no steeper than 1° in all directions?** : Yes\_ \_Meets\_ Standard (Rating: 1)

### Access Routes

**From:** : piinewood st

**To:** : Ginter's Trail

**2. What is the condition of the surface along this route?** : Good

**4. What is the type of surface?** : Asphalt

### Clear Width

**5. What is the typical route width (mm)?** : More\_than\_1525 (Rating: 0)

**Comments/Description** : post at entrance with about 700mm clear on each side See photo. There is a 100mm curb at sidewalk with no letdown for wheelchair access. See photo.

**6. What is the narrowest route width (mm)?** : More\_than\_1525 (Rating: 0)

**Comments/Description** : south side of post

**Comments/Description** : roots cracks etc.see photo

**8. If yes, are the obstacles at least 1220mm apart?** : No (Rating: 0)

**9. If the route is anything other than concrete, asphalt or boardwalk, are there any obstacles that exceed 25mm from the surface?** : N\_A (Rating: 0)

**10. If yes, are the obstacles at least 1220mm apart?** : N\_A (Rating: 0)

## Openings

11. Are there any gaps or grates present that have an opening greater than 13mm? : No (Rating: 0)

12. If gaps/grates are present, do they run perpendicular to the path of travel? : N\_A (Rating: 0)

## Running Slope

13. What is the typical running slope on the route? : Flat\_Gentle\_1\_or\_less

14. What is the maximum running slope on the route? : Moderate\_2\_-\_3 (Rating: 1)

Comments/Description : At entrance.

## Cross Slope

15. What is the typical cross slope on the route? : Flat\_Gentle\_1\_or\_less

16. What is the maximum cross slope on the route? : Flat\_Gentle\_1\_or\_less

## Resting Intervals

17. Are there resting intervals at the top and bottom of a route where the grade exceeds 3°? : N\_A (Rating: 0)

18. If the running slope is greater than 3°, are there resting intervals in the middle of the route when the length exceeds 9.1m? : N\_A (Rating: 0)

## Benches

21. Are there any benches along the route? : No (Rating: 0)

22. If yes, are the benches located approximately every 61m? : N\_A (Rating: 0)

23. Is the bench seat height between 485mm - 510mm? : N\_A (Rating: 0)

## Ramps

24. Is there is a ramp? : No (Rating: 0)

25. Is the ramp at least 915mm wide?

Note: If there are handrails, measure between the handrails. : N\_A (Rating: 0)

26. Is the surface stable, firm and slip resistant? : N\_A (Rating: 0)

27. For each section of the ramp, is the running slope no greater than 5°?

Note: Rises no greater than 76mm with a slope no steeper than 7° and rises no greater than 150mm with a slope no steeper than 6° are permitted when due to space limitations. : N\_A (Rating: 0)

28. Is there a level landing that is at least 1525mm long and at least as wide as the ramp: At the top of the ramp? : N\_A (Rating: 0)

**29. At the bottom of the ramp? : N\_A (Rating: 0)**

**30. Is there a level landing where the ramp changes direction that is at least 1525mm x 1525mm? : N\_A (Rating: 0)**

**31. If the ramp has a rise higher than 150mm are there handrails on both sides? : N\_A (Rating: 0)**

**32. Is the top of the handrail gripping surface no less than 865mm and no greater than 965mm above the ramp surface? : N\_A (Rating: 0)**

**33. Is the handrail gripping surface continuous and not obstructed along the top or sides? : N\_A (Rating: 0)**

**34. If there are obstructions, is the bottom of the gripping surface obstructed no more than 20%? : N\_A (Rating: 0)**

### **Stairs**

**35. Are there floors or surfaces connected only by stairs, not an elevator or ramp? : No (Rating: 0)**

**36. How many flights of stairs are there? : N\_A**

**37. If there are less than a flight, how many stairs are there? : N\_A**

**38. Do all stair treads have a horizontal strip at the edge that is: 40mm-60mm deep, colour contrasted & extends the full width of the step? : N\_A (Rating: 0)**

**39. If the stairs are not enclosed, is there a tactile warning system present at the landing of entrance to stairs system? : N\_A (Rating: 0)**

**40. Are there handrails on both sides of the stairs at a uniform height of 860mm-920mm above the front step? : N\_A (Rating: 0)**

**41. Do the handrails extend horizontally at the top and bottom of each flight of stairs? : N\_A (Rating: 0)**

**42. Are the handrails continuous around landings? : N\_A (Rating: 0)**

**43. Are the handrails continuously graspable, without interruption by vertical supports, newel posts, or other construction elements which require repositioning the hands while ascending or descending? : N\_A (Rating: 0)**

**44. Do the handrails have a graspable cross-section that is either circular with an outside diameter of 30mm-40mm or elliptical with an outside perimeter of 100mm-125mm? : N\_A (Rating: 0)**

### **Trails**

**Date of Audit : 2016-08-17**

**Name of Trail : Ginter Homestead**

**Section of trail audited : Massey parking lot to Ginter Homestead**

**Weather condition during audit : Sunny**



### Clear Width

5. What is the typical trail width (mm)? : More\_than\_1525 (Rating: 0)

6. What is the narrowest trail width (mm)? : More\_than\_1525 (Rating: 0)

### Obstacles

7. If the trail is concrete, asphalt or boardwalk, are there any obstacles that exceed 13mm from the surface? : No (Rating: 0)

Comments/Description : roots cracks frostheaves

8. If yes, are the obstacles at least 1220mm apart? : No (Rating: 0)

9. If the trail is anything other than concrete, asphalt or boardwalk, are there any obstacles that exceed 25mm from the surface? : N\_A (Rating: 0)

10. If yes, are the obstacles at least 1220mm apart? : N\_A (Rating: 0)

### Openings

11. Are there any gaps or grates present that have an opening greater than 13mm? : No (Rating: 0)

12. If gaps/grates are present, do they run perpendicular to the path of travel? : N\_A (Rating: 0)

Comments/Description : some sections exceed 7deg.

### Resting Intervals

17. Are there resting intervals at the top and bottom of a trail where the grade exceeds 3°? : No (Rating: 0)

18. If the running slope is greater than 3°, are there resting intervals in the middle of the trail when the length exceeds 9.1m? : N\_A (Rating: 0)

### Benches

21. Are there any benches along the trail? : No (Rating: 0)

22. If yes, are the benches located approximately every 61m? : N\_A (Rating: 0)

**23. Is the bench seat height between 485mm - 510mm? : N\_A (Rating: 0)**

### **Ramps**

**24. Is there is a ramp? : No (Rating: 0)**

**25. Is the ramp at least 915mm wide?**

**Note: If there are handrails, measure between the handrails. : N\_A (Rating: 0)**

**26. Is the surface stable, firm and slip resistant? : N\_A (Rating: 0)**

**27. For each section of the ramp, is the running slope no greater than 5°?**

**Note: Rises no greater than 76mm with a slope no steeper than 7° and rises no greater than 150mm with a slope no steeper than 6° are permitted when due to space limitations. : N\_A (Rating: 0)**

**28. Is there a level landing that is at least 1525mm long and at least as wide as the ramp: At the top of the ramp? : N\_A (Rating: 0)**

**29. At the bottom of the ramp? : N\_A (Rating: 0)**

**30. Is there a level landing where the ramp changes direction that is at least 1525mm x 1525mm? : N\_A (Rating: 0)**

**31. If the ramp has a rise higher than 150mm are there handrails on both sides? : N\_A (Rating: 0)**

**32. Is the top of the handrail gripping surface no less than 865mm and no greater than 965mm above the ramp surface? : N\_A (Rating: 0)**

**33. Is the handrail gripping surface continuous and not obstructed along the top or sides? : N\_A (Rating: 0)**

**34. If there are obstructions, is the bottom of the gripping surface obstructed no more than 20%? : N\_A (Rating: 0)**

### **Stairs**

**35. Are there floors or surfaces connected only by stairs, not an elevator or ramp? : No (Rating: 0)**

**Comments/Description : one side trail has stairs for access -see photo**

**36. How many flights of stairs are there? : N\_A**

**37. If there are less than a flight, how many stairs are there? : N\_A**

**38. Do all stair treads have a horizontal strip at the edge that is: 40mm-60mm deep, colour contrasted & extends the full width of the step? : N\_A (Rating: 0)**

**Comments/Description : gavel stairs with dimensional lumber risers. 50mm lip down from asphalt to first tread. treads vary from 560 to 520mm. risers vary from 80 to 120mm**

**39. If the stairs are not enclosed, is there a tactile warning system present at the landing of entrance to stairs system? : No (Rating: 0)**

**40. Are there handrails on both sides of the stairs at a uniform height of 860mm-920mm above the front step? : No - Below Standard (Rating: 0)**

**41. Do the handrails extend horizontally at the top and bottom of each flight of stairs? : N\_A (Rating: 0)**

**42. Are the handrails continuous around landings? : N\_A (Rating: 0)**

**43. Are the handrails continuously graspable, without interruption by vertical supports, newel posts, or other construction elements which require repositioning the hands while ascending or descending? : N\_A (Rating: 0)**

**44. Do the handrails have a graspable cross-section that is either circular with an outside diameter of 30mm-40mm or elliptical with an outside perimeter of 100mm-125mm? : N\_A (Rating: 0)**

**Comments/Description : Homestead site provides a view of Prince George but no viewing aids provided**

**2. Is there sufficient clear ground space, a minimum of 915mm x 1220mm for the user to view the key features? : N\_A (Rating: 0)**

**4. What type of surface is the viewing area? : Concrete**

**5. Is there a clear space between 815mm - 1320mm above the ground, free of obstructions and extending the full width of clear space? : Yes - Meets Standard (Rating: 1)**

#### **Picnic Area**

**1. Are picnic tables provided? : No (Rating: 0)**

**2. How many accessible picnic tables are there? : N\_A**

**3. If the picnic table is up to 2.7m long, is there one wheelchair seating space? : N\_A (Rating: 0)**

**4. If the picnic table is longer than 2.7m, are there at least two wheelchair spaces provided? : N\_A (Rating: 0)**

**5. Is there clear and level ground space, 915mm measured from back edge of seats/benches? : N\_A (Rating: 0)**

**6. Do the accessible spaces have adequate knee clearance, 685mm high x 760mm wide x 430mm deep? : N\_A (Rating: 0)**

**7. Is the ground surface surrounding the accessible picnic table firm and stable? : N\_A (Rating: 0)**

**8. Is there a clear, level accessible route to the picnic table? : N\_A (Rating: 0)**

#### **Shelters**

**1. Are there any camp shelters? : No (Rating: 0)**

**2. What is the slope at the entrance to the camp shelter? : N\_A (Rating: 0)**

**3. What type of surface is in the camp shelter? : N\_A**

**4. Is the shelter surface firm and stable?** : N\_A (Rating: 0)

**5. Is there a clear, level accessible route to the camp shelter?** : N\_A (Rating: 0)

### Benches

**1. Are any benches provided?** : No (Rating: 0)

**2. If yes, how many benches are there?** : N\_A

**4. Is there a minimum of 915mm x 1220mm clear ground space beside the bench?** : N\_A (Rating: 0)

**5. Is there a clear, level accessible route to the bench?** : N\_A (Rating: 0)

### Measurement

**(mm)** : 980

**Comments/Description** : bear proof - located at trail head (980mm high) accessible at Massey park lot end (800mm high).

**4. If there are operable parts, can they be operated using one hand, without tightly grasping, pinching, or twisting the wrist and with no more than 2.3kg of force?** : No (Rating: 0)

**Comments/Description** : bear proof

### Campfires & Grills

**1. Is there an area for campfires?** : No (Rating: 0)

**2. Is there a minimum of 1220mm clear ground space on all sides?** : N\_A (Rating: 0)

**3. Is the slope 3° or less in all directions?** : N\_A (Rating: 0)

**4. Is the grill height between 380mm - 865mm above the ground?** : N\_A (Rating: 0)

**5. Is the fire building surface height at least 230mm above the ground?** : N\_A (Rating: 0)

**6. If there is a raised edge or wall around the fire building area, is the thickness less than 255mm?** : N\_A (Rating: 0)

**7. Is there a clear, level accessible route to the campfire area?** : N\_A (Rating: 0)

**1. Are any public washrooms located at the trail head or on the trail?** : No

**Additional comments regarding assessment** : Majority of trail would be considered quite steep for a manual wheelchair.



**Description of Photo 1 :** Branch path off of main trail. Not wheelchair accessible



**Description of Photo 2 :** Branch path off of main trail. Steep and bridge has ridges up to 50mm high in center.



**Description of Photo 3 :** showing accessible but bearproof bin on trail

**Description of Photo 4 :** Showing a non accessible branch trail

Washrooms

Camping

Water Access

Goods and Services